To: McGrath, Shaun[McGrath.Shaun@epa.gov]

From: Card, Joan

Sent: Thur 8/13/2015 5:02:02 PM

Subject: RE: Gold King Site - Situation Update 8-13-15; 1000 hour

Got it.

From: McGrath, Shaun

Sent: Thursday, August 13, 2015 10:54 AM

To: Card, Joan

Subject: Fwd: Gold King Site - Situation Update 8-13-15; 1000 hour

For 1:00 call

Sent from my iPhone

Begin forwarded message:

From: "Hestmark, Martin" < Hestmark. Martin@epa.gov >

Date: August 13, 2015 at 10:52:17 AM MDT

To: "McGrath, Shaun" < McGrath. Shaun@epa.gov >, "Card, Joan" < Card. Joan@epa.gov >,

"Bohan, Suzanne" <bohan.suzanne@epa.gov>, "Ward, W. Robert"

< <u>Ward.Robert@epa.gov</u>>, "Ostrander, David" < <u>Ostrander.David@epa.gov</u>>

Subject: Fwd: Gold King Site - Situation Update 8-13-15; 1000 hour

FYI

Sent from my iPhone

Begin forwarded message:

From: "Way, Steven" < way.steven@epa.gov>

Date: August 13, 2015 at 10:21:40 AM MDT

To: "Myers, Craig" < <u>Myers.Craig@epa.gov</u>>, "Peterson, Cynthia"

<<u>Peterson.Cynthia@epa.gov</u>>, "Hestmark, Martin" <<u>Hestmark.Martin@epa.gov</u>>,

"Ostrander, David" < Ostrander. David@epa.gov>

Cc: "Merritt, Steven" < Merritt. Steven@epa.gov>, "Williams, Laura"

<williams.laura@epa.gov>

Subject: Gold King Site - Situation Update 8-13-15; 1000 hour

Notice: During morning operations the contractor determined it necessary to begin constructing an additional containment basin to supplement the current

treatment/settling ponds. This activity required disturbance of soil/rock in and adjacent to the Cement Creek. The sediment is releasing iron precipitate to the creek. This is similar to routinely released sediments from this district during precipitation and spring run-off.

Steven Way

Federal On-Scene Coordinator

Emergency Response Unit

US EPA - Region 8

1595 Wynkoop Street

Denver, CO 80202

Office: 303-312-6723